

Appl. No. 10/016,132

Response dated February 17, 2005

Reply to Office Action mailed November 17, 2004

Amendments to the Specification:

Please replace the paragraph beginning at page 9, line 7, with the following amended paragraph:

Figure 2 shows the first face 115 face of first reactor plate 200, which forms a portion of the reaction chamber 119. The first reactor plate 200 is preferably rectangular in shape and has two ports at each end thereof. At one end, a solution inlet 236 and a coolant outlet 240 are provided. At the opposite end, a solution outlet 237 and a coolant inlet 241 are provided. The rim 250 and gasket 400 surrounds the coolant inlet 241 and coolant outlet 240 to prevent the coolant from entering the reaction chamber 119. A solution flow field 232 preferably having a number of open-faced parallel tortuous channels 235 is formed within the first face 115 of the first reactor plate 200. The channels 235 extend between the solution inlet 236 and the solution outlet 237. The solution inlet 236 and solution outlet 237 for chemical hydride solution communicate with the first and second solution connection ports 314, 315, respectively.

BEST AVAILABLE COPY

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☒ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.